EDGE 2 – Software Update Version 5.3.2

CORRECTIONS & FIXES

Stability

Unable to Install New Software Versions in Some Systems

- Fixed an issue that could cause extremely slow Ethernet communication when the speed limiter is enabled, potentially preventing software updates from being downloaded.
- Only affects CPU blue board with black heat sink.
- Affected official versions: 5.2.3, 5.2.4 and 5.3.1
- Affected beta versions: 5.0.6, 5.0.7, 5.0.8, 5.1.6, 5.1.7 and 5.3.0
- Version 5.3.2 resolves the issue and helps ensure successful installation of future software releases.
- Customers experiencing update difficulties should contact Technical Support for assistance.

AP and Cumberland reserve the right to change designs and specifications without notice. Copyright © 2026 GSI Group LLC. All rights reserved.