





NOTE: For access to the input pressure tap on the 20-5070 or 20-5071 replacement gas valve, a hole or slot must be drilled or cut into the outer wrap as shown in the figure.

Existing valve cutout



11/16"



2-3/8"

