



Alert Alarm III



The main function of the alarm sources display is to inform the operator about the status of the machine. The red lights will on if there is any abnormal condition occurred and indicates which source(s) have caused the alarm condition.

These Limit set points consist of high and low limit. When it detects the temperature reaches the high/low limit, it will trigger the alarm. When this happens, main controller might be faulty.

- Test button is use to check the siren is workable or not.
- For the power switch it can disconnects the entire power source to the battery and board.

FEATURE FUNCTIONS:

- It detects high limit and low limit set point temperatures. If any of this do not meet the requirement, it will trigger the alarm signal.
- It can be equip with 2 temperature sensors and 2 auxiliary inputs from other controllers.
- It has built in battery backup that can last up to 2 hours.
- Has its own siren backup.
- Power Supply : 120VAC or 240VAC 50/60 HZ
- Temperature Range : 0 – 55 degree Celsius
- Outputs :1 @ 12VDC and 1 AMP Inputs
- 2 thermistor temperature another TC4-4SD board to work as slave.



Plot 218, Jalan Perindustrian Bukit Minyak 6,
Kawasan Perindustrian Bukit Minyak,
14100 Simpang Ampat, Penang, Malaysia.
Tel: 604 505 7598 Fax: 604 505 9879



Cumberland & AP are part of GSI, a worldwide Brands of AGCO
Copyright © 2017 by AGCO GSI Malaysia | Due to continual improvements,
Cumberland & AP reserves the right to change designs and specifications without notice.

For more information on our AP and Cumberland's products and services,
contact your local representative or visit us online at :

www.gsiasia.net